Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 12/2/2015 (Half), 12/3/2015	Man Days: 1.5
Inspection Unit: Robinson	·
Location of Audit: Robinson	
Exit Meeting Contact:	
Inspection Type: Standard Inspection - Field Audit	
Pipeline Safety Representative(s): Charles Gribbins	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

Headquarters Address Information:	300 Liberty		
	Peoria, IL 61602		
	Emergency Phone#: (800) 755-5000		
	Fax#:		
Official or Mayor's Name:	Ron Pate		
	Phone#: (217) 424-6518		
	Email:		
Inspection Contact(s)	Title	Phone No.	
Kevin Glaspy	Quality Assurance Consultant	(217) 820-4221	
Robert Roth	Superintendent of Quality Assurance	(217) 778-0785	

CUSTOMER METER & REGULATOR	Status
Category Comment:	
Customer meter inspections were checked at the following locations.	
702 W Walnut steel	
704 W Walnut steel	
706 W Walnut steel	
708 W Walnut plastic	
802 W Walnut plastic	
804 W Walnut plastic	
806 W Walnut plastic	
808 W Walnut steel	
810 W Walnut steel	
807 W Walnut steel	
805 W Walnut steel	
803 W Walnut steel	
801 W Walnut steel	
709 W Walnut steel	

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

707 W Walnut steel 705 W Walnut steel 701 W Walnut Plastic		
2035 Parrire Street steel [192.353(a)]	Is the customer meter and regulator installed in a readily accessible location and protected from corrosion and other damage, including if installed outside a building, vehicular damage that may be anticipated?	Satisfactory
[192.355(b)(1)]	Is the customer regulator vent rain and insect resistant?	Satisfactory
[192.355(b)(2)]	Is the customer regulator vent located where gas from the vent escapes freely into the atmosphere and away from building openings?	Satisfactory
[192.355(b)(3)]	Is the vent protected from damage caused by submergence in areas of flooding?	Not Checked
General Comment:		
Staff did not encounter any are	eas during this inspection that were in areas where submergence was an issue.	
[192.357(a)]	Is the customer meter and regulator installed to minimize anticipated stresses upon connecting piping?	Satisfactory
[192.357(d)]	Is a customer regulator that might release gas vented to the outside atmosphere?	Satisfactory
[192.359(a)]	Is the meter operating pressure within the allowable limits of the meter case rating?	Satisfactory
[192.365(a)]	Is the service line valve upstream of the regulator or meter?	Satisfactory
[192.365(c)]	Is the underground service line valve located in a curb box or standpipe that allows for ready operation?	Not Checked
General Comment:		
Staff did not encounter any un	der ground service line valves in the area of this inspection.	
[192.727(d)][192.727(d)]	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?	Not Checked
General Comment:		
Staff did not encounter any an	y services that had been discontinued during this field inspection.	
	CATHODIC PROTECTION	Status
[192.463(a)]	Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?	Satisfactory
[192.465(a)]	Were pipe to soil readings taken?	Satisfactory
General Comment: Pipe to soil readings were take 702 W Walnut -1.106 volts 704 W Walnut -1.106 volts 808 W Walnut -1.285 volts 810 W Walnut -1.112 volts	en at the following locations:	

810 W Walnut -1.112 volts 807 W Walnut -1.172 volts

General Comment: Staff did not inspect any rectifiers during this field inspection in the Robinson Service area. 192.465(a)] Were isolated mains/services tested? Not Checked General Comment: Staff did not verify any isolated mains/services during this field audit. 192.465(c)] Were critical/non critical bonds tested? Not Checked General Comment: Staff did not verify and bonds during this inspection. 192.467(a)] Is electrical isolation provided by use of insulated meter spud, valve, union, or flange? Seneral Comment: All facilities were checked for proper isolation methods. 192.467(c)] Were casings installations tested for electrical isolation? Not Checked General Comment: Staff did not verify any casings were in the area at the time of this audit. 192.479(a)] Is the above ground piping coated or painted as required? Satisfactory General Comment: All above ground piping was found to have been painted at the regulating stations. 192.479(c)] Is the pipeline free of corrosion or pitting? Satisfactory General Comment: There was no corrosion or pitting on any of the above grade piping at the regulating stations. DAMAGE PREVENTION Status Not Checked Satisfactory One of planned excavation activities? Not Checked Satisfactory One of planned excavation activities?	805 W Walnut -1.327 volts 803 W Walnut -1.336 volts 709 W Walnut -1.206 volts 707 W Walnut -1.208 volts 705 W Walnut -1.290 volts 2035 Parrire -1.273 volts	S S S S	
Staff did not inspect any rectifiers during this field inspection in the Robinson Service area. 192.465(a)] Were isolated mains/services tested? Not Checked General Comment: Staff did not verify any isolated mains/services during this field audit. 192.465(c)] Were critical/non critical bonds tested? Not Checked General Comment: Staff did not verify and bonds during this inspection. 192.467(a)] Is electrical isolation provided by use of insulated meter spud, valve, union, or flange? Seneral Comment: All facilities were checked for proper isolation methods. 192.467(c)] Were casings installations tested for electrical isolation? Not Checked General Comment: Staff did not verify any casings were in the area at the time of this audit. 192.479(a)] Is the above ground piping coated or painted as required? Satisfactory General Comment: All above ground piping was found to have been painted at the regulating stations. 192.479(c)] Is the pipeline free of corrosion or pitting? Satisfactory General Comment: There was no corrosion or pitting on any of the above grade piping at the regulating stations. DAMAGE PREVENTION Status Not Checked General Comment: Does the operator have a valid notification of planned excavation activities? Not Checked General Comment:	[192.465(b)]	Were rectifier installations inspected?	Not Checked
Mot Checked Seneral Comment: Staff did not verify any isolated mains/services tested? Not Checked Seneral Comment: Staff did not verify any isolated mains/services during this field audit.	General Comment:		
General Comment: Staff did not verify any isolated mains/services during this field audit. 192.465(c)] Were critical/non critical bonds tested? Not Checked General Comment: Staff did not verify and bonds during this inspection. 192.467(a)] Is electrical isolation provided by use of insulated meter spud, valve, union, or flange? General Comment: All facilities were checked for proper isolation methods. 192.467(c)] Were casings installations tested for electrical isolation? Not Checked General Comment: Staff did not verify any casings were in the area at the time of this audit. 192.479(a)] Is the above ground piping coated or painted as required? Satisfactory General Comment: All above ground piping was found to have been painted at the regulating stations. 192.479(c)] Is the pipeline free of corrosion or pitting? Satisfactory General Comment: There was no corrosion or pitting on any of the above grade piping at the regulating stations. DAMAGE PREVENTION Status Not Checked General Comment: Does the operator have a valid notification of planned excavation activities? Not Checked General Comment:	Staff did not inspect any re	ectifiers during this field inspection in the Robinson Service area.	
Staff did not verify any isolated mains/services during this field audit. 192.465(c)] Were critical/non critical bonds tested? Seneral Comment: Staff did not verify and bonds during this inspection. 192.467(a)] Is electrical isolation provided by use of insulated meter spud, valve, union, or flange? General Comment: All facilities were checked for proper isolation methods. 192.467(c)] Were casings installations tested for electrical isolation? Not Checked General Comment: Staff did not verify any casings were in the area at the time of this audit. 192.479(a)] Is the above ground piping coated or painted as required? Satisfactory General Comment: All above ground piping was found to have been painted at the regulating stations. 192.479(c)] Is the pipeline free of corrosion or pitting? Satisfactory General Comment: There was no corrosion or pitting on any of the above grade piping at the regulating stations. DAMAGE PREVENTION Status Not Checked General Comment: Does the operator have a valid notification of planned excavation activities? Not Checked General Comment:	[192.465(a)]	Were isolated mains/services tested?	Not Checked
Mot Checked Seneral Comment: Staff did not verify and bonds during this inspection.	General Comment:		
General Comment: Staff did not verify and bonds during this inspection. [192.467(a)] Is electrical isolation provided by use of insulated meter spud, valve, union, or flange? [192.467(c)] Is electrical isolation methods. [192.467(c)] Were casings installations tested for electrical isolation? [192.467(c)] Were casings installations tested for electrical isolation? [192.467(c)] Is the above ground piping coated or painted as required? [192.479(a)] Is the above ground piping coated or painted as required? [192.479(c)] Is the pipeline free of corrosion or pitting? [192.479(c)] Is the pipeline free of corrosion or pitting? [192.479(c)] Is the pipeline free of corrosion or pitting at the regulating stations. [192.479(c)] Is the pipeline free of corrosion or pitting at the regulating stations. [192.479(c)] Does the operator have a valid notification of planned excavation activities? [192.614] Does the operator have a valid notification of planned excavation activities? [192.614] Not Checked General Comment:	Staff did not verify any iso	lated mains/services during this field audit.	
Staff did not verify and bonds during this inspection. [192.467(a)] Is electrical isolation provided by use of insulated meter spud, valve, union, or flange? [392.467(a)] Is electrical isolation provided by use of insulated meter spud, valve, union, or flange? [392.467(c)] Were casings installations tested for electrical isolation? [392.467(c)] Were casings installations tested for electrical isolation? [392.467(c)] Is the above ground piping coated or painted as required? [392.479(a)] Is the above ground piping coated or painted as required? [392.479(c)] Is the pipeline free of corrosion or pitting? [392.479(c)] Is the pipeline free of corrosion or pitting? [392.479(c)] Satisfactory [392.479(c)] Is the pipeline free of corrosion or pitting? [392.479(c)] DAMAGE PREVENTION [402.614] Does the operator have a valid notification of planned excavation activities? [403.400] Not Checked General Comment:	[192.465(c)]	Were critical/non critical bonds tested?	Not Checked
Is electrical isolation provided by use of insulated meter spud, valve, union, or flange? General Comment: All facilities were checked for proper isolation methods. (192.467(c)] Were casings installations tested for electrical isolation? Not Checked General Comment: (192.479(a)] Is the above ground piping coated or painted as required? Satisfactory General Comment: All above ground piping was found to have been painted at the regulating stations. (192.479(c)] Is the pipeline free of corrosion or pitting? Satisfactory General Comment: There was no corrosion or pitting on any of the above grade piping at the regulating stations. DAMAGE PREVENTION Status Not Checked General Comment:	General Comment:		
flange? General Comment: All facilities were checked for proper isolation methods. 192.467(c)] Were casings installations tested for electrical isolation? Not Checked General Comment: Staff did not verify any casings were in the area at the time of this audit. 192.479(a)] Is the above ground piping coated or painted as required? Satisfactory General Comment: All above ground piping was found to have been painted at the regulating stations. 192.479(c)] Is the pipeline free of corrosion or pitting? Satisfactory General Comment: There was no corrosion or pitting on any of the above grade piping at the regulating stations. DAMAGE PREVENTION Status 192.614] Does the operator have a valid notification of planned excavation activities? Not Checked General Comment:	Staff did not verify and bo	nds during this inspection.	
All facilities were checked for proper isolation methods. [192.467(c)] Were casings installations tested for electrical isolation? Not Checked General Comment: [Staff did not verify any casings were in the area at the time of this audit. [192.479(a)] Is the above ground piping coated or painted as required? Satisfactory [General Comment: [All above ground piping was found to have been painted at the regulating stations. [192.479(c)] Is the pipeline free of corrosion or pitting? Satisfactory [General Comment: [There was no corrosion or pitting on any of the above grade piping at the regulating stations. [192.614] Does the operator have a valid notification of planned excavation activities? Not Checked General Comment:	[192.467(a)]		Satisfactory
Mere casings installations tested for electrical isolation? Not Checked General Comment: Staff did not verify any casings were in the area at the time of this audit. [192.479(a)] Is the above ground piping coated or painted as required? Satisfactory General Comment: All above ground piping was found to have been painted at the regulating stations. [192.479(c)] Is the pipeline free of corrosion or pitting? Satisfactory General Comment: There was no corrosion or pitting on any of the above grade piping at the regulating stations. DAMAGE PREVENTION Status 192.614] Does the operator have a valid notification of planned excavation activities? Not Checked General Comment:	General Comment:		
General Comment: Staff did not verify any casings were in the area at the time of this audit. [192.479(a)] Is the above ground piping coated or painted as required? [392.479(a)] Satisfactory [392.479(c)] Is the pipeline free of corrosion or pitting? [392.479(c)] Is the pipeline free of corrosion or pitting? [392.479(c)] Satisfactory [392.479(c)] Shappend Satisfactory [392.479(c)] DAMAGE PREVENTION [492.479(c)] Status [492.479(c)] Does the operator have a valid notification of planned excavation activities? [492.479(c)] Not Checked Seneral Comment:	All facilities were checked	for proper isolation methods.	
Staff did not verify any casings were in the area at the time of this audit. [192.479(a)] Is the above ground piping coated or painted as required? [192.479(a)] Satisfactory [192.479(c)] Is the pipeline free of corrosion or pitting? [192.479(c)] Satisfactory [192.479(c)] Satisfactory [192.479(c)] DAMAGE PREVENTION [192.479(c)] Status [193.614] Does the operator have a valid notification of planned excavation activities? [193.614] Seneral Comment:	[192.467(c)]	Were casings installations tested for electrical isolation?	Not Checked
Satisfactory General Comment: All above ground piping was found to have been painted at the regulating stations. In 192.479(c)] Is the pipeline free of corrosion or pitting? General Comment: There was no corrosion or pitting on any of the above grade piping at the regulating stations. DAMAGE PREVENTION Status 192.614] Does the operator have a valid notification of planned excavation activities? Not Checked General Comment:	General Comment:	<u> </u>	
General Comment: All above ground piping was found to have been painted at the regulating stations. [192.479(c)] Is the pipeline free of corrosion or pitting? General Comment: There was no corrosion or pitting on any of the above grade piping at the regulating stations. DAMAGE PREVENTION Status 192.614] Does the operator have a valid notification of planned excavation activities? Not Checked General Comment:	Staff did not verify any cas	sings were in the area at the time of this audit.	
All above ground piping was found to have been painted at the regulating stations. [192.479(c)] Is the pipeline free of corrosion or pitting? [General Comment: There was no corrosion or pitting on any of the above grade piping at the regulating stations. [192.614] Does the operator have a valid notification of planned excavation activities? [192.614] Received the comment: [192.615] Received the comment: [192.616] Received the comment: [192.616] Received the comment: [192.617] Received the comment: [192.618] Recei	[192.479(a)]	Is the above ground piping coated or painted as required?	Satisfactory
Is the pipeline free of corrosion or pitting? Satisfactory General Comment: There was no corrosion or pitting on any of the above grade piping at the regulating stations. DAMAGE PREVENTION Status 192.614] Does the operator have a valid notification of planned excavation activities? Not Checked General Comment:	General Comment:		
General Comment: There was no corrosion or pitting on any of the above grade piping at the regulating stations. DAMAGE PREVENTION Status 192.614] Does the operator have a valid notification of planned excavation activities? Not Checked General Comment:	All above ground piping w	as found to have been painted at the regulating stations.	
There was no corrosion or pitting on any of the above grade piping at the regulating stations. DAMAGE PREVENTION Status 192.614] Does the operator have a valid notification of planned excavation activities? Not Checked General Comment:	[192.479(c)]	Is the pipeline free of corrosion or pitting?	Satisfactory
DAMAGE PREVENTION 192.614] Does the operator have a valid notification of planned excavation activities? Not Checked General Comment:	General Comment:		
Does the operator have a valid notification of planned excavation activities? Not Checked General Comment:	There was no corrosion or	r pitting on any of the above grade piping at the regulating stations.	
General Comment:		DAMAGE PREVENTION	Status
	[192.614]	Does the operator have a valid notification of planned excavation activities?	Not Checked
Staff did not inspect any excavation activities during this inspection	General Comment:		
	Staff did not inspect any e	excavation activities during this inspection	
Did the operator complete the locating activities in the specified timeframe? Not Checked	[265.40(a)]	Did the operator complete the locating activities in the specified timeframe?	Not Checked

General Comment:		
Staff did not inspect any exc	eavation activities during this inspection	
[192.614(c)(5)]	Were temporary markings made in accordance with the operator's Operation and Maintenance Manual?	Not Checked
General Comment:	·	
Staff did not inspect any exc	eavation activities during this inspection	
[192.707(a)(1)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located at each crossing of a public road and railroad?	Satisfactory
General Comment:		
Staff inspected line markers	at the regulating stations and several railroad crossings all the required information was found on the signs	
[192.707(a)(2)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located wherever necessary to identify the location of the transmission line or main to reduce the possibility of damage or interference?	Satisfactory
[192.707(c)]	Are line markers placed and maintained as close as practical over each main and transmission line located above ground?	Satisfactory
[192.707(d)(1)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The word "Warning," "Caution," or "Danger" followed by the words "Gas (or name of gas transported) Pipeline" all of which, except for markers in heavily developed urban areas, must be in letters at least 1 inch (25 millimeters) high with ¼ inch (6.4 millimeters) stroke?	Satisfactory
[192.707(d)(2)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The name and phone number (including area code) of the operator where the operator can be reached at all times?	Satisfactory
PRESSUR	RE LIMITING AND REGULATING DEVICES (MECHANICAL)	Status
Category Comment:		
The following pressure limiting Station ID 335001 Station ID 335022 Station ID 335020 Station ID 335023 Station ID 335024 Station ID 335029	ng stations were inspected: All stations were fouund to have meet the requirements mentioned in this section	on.
[192.739(a)(4)]	Was each pressure limiting station, relief device (except rupture discs), and pressure regulating station and its equipment subjected at intervals not exceeding 15 months, but at least once each calendar year, to inspections and tests to determine that it is properly installed and protected from dirt, liquids, or other conditions that might prevent proper operation.?	Satisfactory

General Comment:		
Staff verified the inspection da	te by having the operator provide the following documents Pressure Control Station Inspection Form.	
[192.317(b)]	Is each above ground transmission line or main protected from accidental damage by vehicular traffic or other similar causes?	Satisfactory
General Comment:	<u> </u>	
The above ground stations are	e protected from damage by distance from the roadway fencing and barricades.	
[192.741(a),192.741(c)]	Were telemetering and/or recording gauges inspected for abnormally high or low pressure indications?	Not Checked
General Comment:		
Staff did not review the teleme	stering at the time of inspection, these indications would be located in Springfield at Ameren Gas Control	Center.
[192.743(a)]	Is overpressure protection provided on the pipeline down stream of the take point?	Not Checked
General Comment:	·	
Staff did not verify the downstr	ream piping to confirm overpressure protection at the time of this inspection.	
[192.199(d)]	Were the pressure relief or pressure limiting devices inspected to determine if the support was made of noncombustible material?	Satisfactory
General Comment:	<u> </u>	
The support for the pressure re	egulation and over pressure devices was made of steel.	
[192.199(e)]	Were the pressure relief or pressure limiting devices inspected to determine if the discharge stacks, vents, or outlet ports were designed to prevent accumulation of water, ice, or snow, and located where gas can be discharged into the atmosphere without undue hazard?	Satisfactory
General Comment:	· · · · · · · · · · · · · · · · · · ·	
Staff inspected the pressure re	elief devices were equipped with a flapper device to prevent accumulation of water, ice, or snow at all loc	cations.
[192.199(h)]	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?	Satisfactory
General Comment:		
The following valves were insp Fire Valve 0097 Fire Valve 0054 Fire Valve 0025 Fire Valve D123 Two other fire valves were insp	pected: Dected at the following stations 3350022 and 335020.	
	VALVE MAINTENANCE	Status
[192.747(a)]	Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench?	Satisfactory
General Comment:		

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Staff inspcted the following valves:

Fire Valve 0097 Fire Valve 0054

Fire Valve 0025

Fire Valve D123

Two other fire valves were inspected at the following stations 3350022 and 335020.

Two other fire valves we	ere inspected at the following stations 3350022 and 335020.	
	ODORIZATION OF GAS	Status
Category Comment:		
Staff did not conduct an	Odor Intensity Level inspection during this field inspection. There was not any Odorization equipment at this local	cation
[192.625(a)]	Was the odor intensity level readily detectable at or below 1/5th LEL?	Not Checked
[192.625(e)]	Was the Odorization equipment and tank levels inspected?	Not Checked
192.625(f)]	Was the operator's equipment calibrated as required?	Not Checked
	TRANSMISSION	Status
[192.179(b)(1)]	Are transmission valves protected from tampering or damage?	Not Checked
General Comment:	·	
There was not any trans	mission valves located in the distribution system.	
[192.745(a)]	Were the valves inspected accessible?	Not Checked
General Comment:	<u> </u>	
There was not any trans	emission valves located in the distribution system.	
[192.719(a)]	Is pre-tested transmission pipe inventory maintained for use in an emergency?	Not Checked
General Comment:	·	
Staff did not inspect any	components or pipes for the required markings during this inspection.	
[192.179(c)]	If blow down activities were observed, were the blow down valves properly sized to allow the transmission pipeline to vent as rapidly as practicable and did the blow down vent freely to atmosphere away from any hazards?	Not Checked
General Comment:	·	
Staff did not observe any	y blow down valves on the transmission lines.	
	MARKING OF MATERIAL	Status
[192.63(a)]	Does the operator's components and pipe contain the required markings?	Not Checked
General Comment:	·	
Staff did not inspect any	components or pipes for the required marking during this inspection.	
	OPERATOR QUALIFICATION	Status
Was a PHMSA Form 15 Operator Qualification Field Inspection Protocol Form completed?		No
General Comment:		

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Staff did not conduct any Operator Qualification Field inspections during this audit.